

高雄市旗山區大林段1080地號等21筆土地清理計畫 112年11月10日提送XRF檢測結果

報告編號	採樣日期及時間	樣品名稱	樣品編號	檢測項目(ppm)		
				鉻	鉛	鋅
R1124552011	112/11/10 10:38-13:24	1121110-1	O1121110M	450	12.0	90
		1121110-2	O1121110N	472	11.0	78
		1121110-3	O1121110O	474	11.0	91
		1121110-4	O1121110P	465	11.0	84
		1121110-5	O1121110Q	490	<7	70
		1121110-6	O1121110R	452	<7	84
		1121110-7	O1121110S	411	<7	74
		1121110-8	O1121110T	427	<7	74
		1121110-9	O1121110U	478	<7	87
		1121110-10	O1121110V	486	<6	92
		1121110-11	O1121110W	466	<7	74
		1121110-12	O1121110X	452	<7	81
		1121110-13	O1121110Y	411	<7	70
		1121110-14	O1121110Z	475	<7	69
		1121110-15	O1121110AA	409	<7	75
		1121110-16	O1121110AB	415	<7	68
		1121110-17	O1121110AC	431	<7	79
		1121110-18	O1121110AD	395	<6	62
		1121110-19	O1121110AE	445	<7	75
		1121110-20	O1121110AF	475	<7	79
		1121110-21	O1121110AG	390	<6	61
		1121110-22	O1121110AH	436	<7	70
		1121110-23	O1121110AI	495	10.0	92
		1121110-24	O1121110AJ	472	<7	69
		1121110-25	O1121110AK	450	<7	62
		1121110-26	O1121110AL	489	<7	78
		1121110-27	O1121110AM	435	<7	66
		1121110-28	O1121110AN	497	11.0	90
		1121110-29	O1121110AO	475	10.0	80
		1121110-30	O1121110AP	488	11.0	85
		1121110-31	O1121110AQ	492	11.0	91
		1121110-32	O1121110AR	465	10.0	79
		1121110-33	O1121110AS	450	<7	67
		1121110-34	O1121110AT	439	<7	60
		1121110-35	O1121110AU	417	<7	62
		1121110-36	O1121110AV	494	11.0	88
		1121110-37	O1121110AW	455	<7	74
		1121110-38	O1121110AX	466	<7	70
		1121110-39	O1121110AY	470	<7	78
		1121110-40	O1121110AZ	432	<7	69
XRF轉爐石級配料判定標準				<661	<27.9	<170