

高雄市旗山區大林段1080地號等21筆土地清理計畫 113年11月29日提送XRF檢測結果

報告編號	採樣日期及時間	樣品名稱	樣品編號	檢測項目(ppm)		
				鉻	鉛	鋅
AR-24-X4-008190-01	113/11/29 10:22-12:08	1131129-1	808-2024-11002989	517	<8	87
		1131129-2	808-2024-11002990	478	<8	77
		1131129-3	808-2024-11002991	521	<7	75
		1131129-4	808-2024-11002992	493	<7	84
		1131129-5	808-2024-11002993	535	<8	88
		1131129-6	808-2024-11002994	492	<8	69
		1131129-7	808-2024-11002995	511	<8	79
		1131129-8	808-2024-11002996	469	<7	82
		1131129-9	808-2024-11002997	509	<7	74
		1131129-10	808-2024-11002998	534	<8	64
		1131129-11	808-2024-11002999	555	<8	98
		1131129-12	808-2024-11003000	529	<8	82
		1131129-13	808-2024-11003001	547	<7	63
		1131129-14	808-2024-11003002	492	<7	67
		1131129-15	808-2024-11003003	488	<7	72
		1131129-16	808-2024-11003004	463	<7	59
		1131129-17	808-2024-11003005	490	<8	64
		1131129-18	808-2024-11003006	517	<8	78
		1131129-19	808-2024-11003007	539	<8	86
		1131129-20	808-2024-11003008	524	<8	93
		1131129-21	808-2024-11003009	470	<8	92
		1131129-22	808-2024-11003010	495	<7	81
		1131129-23	808-2024-11003011	465	<7	76
		1131129-24	808-2024-11003012	451	<7	70
		1131129-25	808-2024-11003013	433	<7	60
XRF轉爐石級配料判定標準				<661	<27.9	<170