

高雄市旗山區大林段1080地號等21筆土地清理計畫 114年01月23日提送XRF檢測結果

報告編號	採樣日期及時間	樣品名稱	樣品編號	檢測項目(ppm)		
				鉻	鉛	鋅
AR-25-X4-000898-01	114/01/23 11:08-11:10	1140123-1	808-2025-01001370	468	<8	88
		1140123-2	808-2025-01001371	466	<8	92
		1140123-3	808-2025-01001372	518	<8	98
		1140123-4	808-2025-01001373	546	<8	90
		1140123-5	808-2025-01001374	498	<7	84
		1140123-6	808-2025-01001375	460	<7	68
		1140123-7	808-2025-01001376	538	<8	99
		1140123-8	808-2025-01001377	547	<8	78
		1140123-9	808-2025-01001378	531	<8	69
		1140123-10	808-2025-01001379	566	<8	88
		1140123-11	808-2025-01001380	586	<8	92
		1140123-12	808-2025-01001381	537	<7	77
		1140123-13	808-2025-01001382	488	<7	66
		1140123-14	808-2025-01001383	458	<7	60
		1140123-15	808-2025-01001384	468	<7	73
		1140123-16	808-2025-01001385	580	<8	98
		1140123-17	808-2025-01001386	566	<8	95
		1140123-18	808-2025-01001387	548	<8	86
		1140123-19	808-2025-01001388	509	<8	80
		1140123-20	808-2025-01001389	498	<7	68
		1140123-21	808-2025-01001390	465	<7	69
		1140123-22	808-2025-01001391	478	<7	77
		1140123-23	808-2025-01001392	508	<8	85
		1140123-24	808-2025-01001393	538	<8	88
		1140123-25	808-2025-01001394	566	<8	75
		1140123-26	808-2025-01001395	592	<8	97
		1140123-27	808-2025-01001396	588	<8	93
		1140123-28	808-2025-01001397	570	<8	90
		1140123-29	808-2025-01001398	498	<8	88
		1140123-30	808-2025-01001399	466	<7	77
XRF轉爐石級配料判定標準				<661	<27.9	<170