

高雄市旗山區大林段1080地號等21筆土地清理計畫 112年5月19日提送XRF檢測結果

報告編號	採樣日期及時間	樣品名稱	樣品編號	檢測項目(ppm)		
				鉻	鉛	鋅
R1123276011	112/05/19 12:14~15:48	1120519-1	O1120519K	457	10.0	84
		1120519-2	O1120519L	418	11.0	92
		1120519-3	O1120519M	456	9.0	77
		1120519-4	O1120519N	477	10.0	81
		1120519-5	O1120519O	517	<7	86
		1120519-6	O1120519P	502	<8	92
		1120519-7	O1120519Q	478	<7	78
		1120519-8	O1120519R	492	<8	87
		1120519-9	O1120519S	451	<7	72
		1120519-10	O1120519T	429	<8	69
		1120519-11	O1120519U	487	<8	75
		1120519-12	O1120519V	489	<7	84
		1120519-13	O1120519W	566	<8	99
		1120519-14	O1120519X	355	<7	77
		1120519-15	O1120519Y	411	<8	79
		1120519-16	O1120519Z	472	<8	95
		1120519-17	O1120519AA	512	<8	82
		1120519-18	O1120519AB	525	<7	65
		1120519-19	O1120519AC	541	<8	69
		1120519-20	O1120519AD	495	<8	83
		1120519-21	O1120519AE	521	<8	95
		1120519-22	O1120519AF	498	<8	90
		1120519-23	O1120519AG	545	<8	96
		1120519-24	O1120519AH	511	10.0	99
		1120519-25	O1120519AI	493	<8	75
		1120519-26	O1120519AJ	455	<7	69
		1120519-27	O1120519AK	425	<7	62
		1120519-28	O1120519AL	433	<7	68
		1120519-29	O1120519AM	466	<8	88
		1120519-30	O1120519AN	471	<8	81
		1120519-31	O1120519AO	503	<8	83
		1120519-32	O1120519AP	535	<8	96
		1120519-33	O1120519AQ	477	<8	90
		1120519-34	O1120519AR	459	<8	87
		1120519-35	O1120519AS	497	<7	76
		1120519-36	O1120519AT	501	<7	75
		1120519-37	O1120519AU	547	<8	81
		1120519-38	O1120519AV	556	10.0	97
		1120519-39	O1120519AW	480	<8	84
		1120519-40	O1120519AX	506	<8	74
		1120519-41	O1120519AY	515	<8	73
		1120519-42	O1120519AZ	547	<8	80
		1120519-43	O1120519BA	562	<8	88
		1120519-44	O1120519BB	521	<8	72
		1120519-45	O1120519BC	491	9.0	66
		1120519-46	O1120519BD	478	9.0	90
		1120519-47	O1120519BE	462	<8	94
		1120519-48	O1120519BF	504	<7	75
		1120519-49	O1120519BG	485	<7	77
		1120519-50	O1120519BH	493	<8	87
XRF轉爐石級配料判定標準				<661	<27.9	<170