

高雄市旗山區大林段1080地號等21筆土地清理計畫 114年03月14日提送XRF檢測結果

報告編號	採樣日期及時間	樣品名稱	樣品編號	檢測項目(ppm)		
				鉻	鉛	鋅
AR-25-X4-002394-01	114/03/14 09:58-10:00	1140314-1	808-2025-03001515	593	<6	92
		1140314-2	808-2025-03001516	550	<7	67
		1140314-3	808-2025-03001517	620	<6	66
		1140314-4	808-2025-03001518	493	<5.9	54
		1140314-5	808-2025-03001519	563	<7	63
		1140314-6	808-2025-03001520	510	<6	55
		1140314-7	808-2025-03001521	521	<6	61
		1140314-8	808-2025-03001522	513	<6	58
		1140314-9	808-2025-03001523	590	<7	52
		1140314-10	808-2025-03001524	631	<6	68
		1140314-11	808-2025-03001525	585	<5.9	57
		1140314-12	808-2025-03001526	523	<6	63
		1140314-13	808-2025-03001527	576	<6	55
		1140314-14	808-2025-03001528	580	<7	68
		1140314-15	808-2025-03001529	573	<7	57
		1140314-16	808-2025-03001530	545	<5.9	69
		1140314-17	808-2025-03001531	561	<7	72
		1140314-18	808-2025-03001532	578	<6	66
		1140314-19	808-2025-03001533	523	<6	54
		1140314-20	808-2025-03001534	520	<5.9	56
		1140314-21	808-2025-03001535	573	<5.9	62
		1140314-22	808-2025-03001536	521	<6	63
		1140314-23	808-2025-03001537	570	<7	54
		1140314-24	808-2025-03001538	543	<7	58
		1140314-25	808-2025-03001539	603	<6	61
		1140314-26	808-2025-03001540	578	<6	55
		1140314-27	808-2025-03001541	563	<7	50
		1140314-28	808-2025-03001542	585	<5.9	61
		1140314-29	808-2025-03001543	610	<5.9	57
		1140314-30	808-2025-03001544	577	<6	54
XRF轉爐石級配料判定標準				<661	<27.9	<170