

高雄市旗山區大林段1080地號等21筆土地清理計畫 115年02月26日提送XRF檢測結果

報告編號	採樣日期及時間	樣品名稱	樣品編號	檢測項目(ppm)		
				鉻	鉛	鋅
AR-26-X4-002314-01(B)	115/02/26 10:15-10:54	1150226-1	808-2026-02001839	465	<4.2	116
		1150226-2	808-2026-02001840	486	<4.3	114
		1150226-3	808-2026-02001841	452	<4.2	95
		1150226-4	808-2026-02001842	490	<4.2	92
		1150226-5	808-2026-02001843	472	<4.3	98
		1150226-6	808-2026-02001844	480	<4.3	106
		1150226-7	808-2026-02001845	460	<4.2	102
		1150226-8	808-2026-02001846	456	<4.3	94
		1150226-9	808-2026-02001847	490	<4.3	90
		1150226-10	808-2026-02001848	472	<4.2	86
		1150226-11	808-2026-02001849	449	<4.3	84
		1150226-12	808-2026-02001850	472	4.6	93
		1150226-13	808-2026-02001851	493	<4.3	96
		1150226-14	808-2026-02001852	496	<4.3	112
		1150226-15	808-2026-02001853	473	<4.2	104
		1150226-16	808-2026-02001854	452	<4.2	98
		1150226-17	808-2026-02001855	430	<4.3	92
		1150226-18	808-2026-02001856	454	<4.2	82
		1150226-19	808-2026-02001857	420	<4.3	80
		1150226-20	808-2026-02001858	416	<4.3	78
XRF轉爐石級配料判定標準				<661	<27.9	<170